

TOSHIBA TEC B-472 / B-572

Preventive Maintenance Special

Tune-up! and Clean-up!

**ONLY
\$499***



* plus freight charges

20 point inspection & part replacement service

from Century Systems, Inc.

This Comprehensive Tune-up includes:

- | | |
|--|---|
| <ol style="list-style-type: none">1. Replacement and recalibration of gap/black mark detection sensor2. Replacement of ribbon detection sensors3. Replacement and cleaning of ribbon motor gears to prevent breakdown due to dirt and grime4. Inspection and testing of motherboard and parallel board5. Inspection of dispense module6. Inspection and cleaning of cutter unit7. Inspection and testing of stepper and ribbon motors8. Inspection of head-up switch9. Inspection and adjustment of paper guides10. Inspection of supply holder | <ol style="list-style-type: none">11. Inspection of timing belts12. Inspection, alignment and cleaning of printhead13. Inspection and cleaning of cooling fan14. Inspection and cleaning of power supply15. Inspection and cleaning of platen roller, feed roller and pinch roller16. Professional cleaning of electronics compartment17. Professional cleaning of front panel display and circuit boards18. Professional cleaning of printing compartment, including interior case19. Professional cleaning of stainless steel outer case20. Professional packing |
|--|---|

Deluxe Package **only \$549.00***

Includes all of the above services

PLUS Replacement of platen roller and ball bearing holders



**No additional
labor costs if
additional parts
are needed!**

Fast Turnaround!
Your Printer Goes to the
Front of the Line!

**Avoid
Production
Shut Down**

Link to online form: <http://www.centurysystems.com/techsup/pms/pmb472572form.html>